

4.1 PBH1型热金属检测器




图1

外壳形式	带冷却
工作电源	DC12V、DC24V、AC110V、AC220V ± 10%额定电压值
工作温度	-25℃~+70℃；有水冷却时-25℃~+120℃
检测温度	550℃~1400℃(普通型)；300℃~1400℃(低温型)

检测器

